


Green Card Interpretation Guide




Unexposed



PASS No fault




FAIL Small fault




PASS Short to medium dry time




FAIL Medium fault



PASS Excessive dry time. Shorten dry time to 5 minutes or less for Bowie Dick test.



FAIL Large fault



PASS Water spray. Place card in holder upside down if steam cannot be dried.